

VIN: **YV1BZ7056B1106067**Marka: **VOLVO**Model: **XC70 D5**Typ paliwa: **DIESEL**Rodzaj nadwozia: **CROSSOVER**

Data wygenerowania raportu: 2018-10-06 13:39:10 UTC +0200



## WIEK POJAZDU

WG DATY PRODUKCJI / ROKU MODELOWEGO



7 lat(a)



10 mies.

Data produkcji / Rok modelowy: **2010-12-06**

WG PIERWSZEJ REJESTRACJI POJAZDU



- lat(a)



- mies.

Data pierwszej rejestracji: -



## PODSUMOWANIE RAPORTU

## 1. INFORMACJE PODSTAWOWE

Przydatne informacje

Liczba wpisów: 2



Informacje o pojeździe

Liczba wpisów: 49



Informacje o producencie

Liczba wpisów: 2



Poprawność VIN

Niedostępny



Sprawdzenie baz skradzionych pojazdów

Przeszukane bazy: 12, Odnotowano: 0



Akcje serwisowe / usterki

Liczba wpisów: 0



## 2. HISTORIA POJAZDU

Odczytane przebiegi

Liczba wpisów: 1



Historia uszkodzeń

Liczba wpisów: 3



Dziennik użytkowania

Liczba wpisów: 0



Historia cenowa

Liczba wpisów: 0



## 3. INFORMACJE DODATKOWE

Dziennik sprawdzeń

Liczba wpisów: 0



Archiwalne zdjęcia pojazdu

Liczba wpisów: 0



Wyposażenie

Liczba wpisów: 277



# 1. INFORMACJE PODSTAWOWE




## PRZYDATNE INFORMACJE

### ŚREDNI PRZEBIEG POJAZDU

88060

**Uwaga:** Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

### ŚREDNI PRZEBIEG POJAZDÓW



**Uwaga:** Na wykresie przedstawiono średni przebieg wg rocznika samochodów z silnikiem PB i ON.



## INFORMACJE O POJEŹDZIE

LICZBA WPISÓW: 49

VIN: **YV1BZ7056B1106067**



|                         |                            |                       |                         |
|-------------------------|----------------------------|-----------------------|-------------------------|
| Producent               | <b>VOLVO</b>               | Model                 | <b>XC70</b>             |
| Rodzaj nadwozia         | <b>CROSSOVER</b>           | Typ paliwa            | <b>DIESEL</b>           |
| Pojemność silnika [cm3] | <b>2400</b>                | Kraj producenta       | <b>SZWECJA</b>          |
| Rok modelowy            | <b>2011</b>                | Kod koloru lakieru    | <b>45200</b>            |
| Kolor lakieru           | <b>BLACK SAPPHIRE</b>      | Próbka koloru lakieru |                         |
| Wersja                  | <b>SUMMUM</b>              | Data produkcji        | <b>2010-12-06</b>       |
| Kod silnika             | <b>D5244T10</b>            | Silnik                | <b>D5</b>               |
| Numer seryjny silnika   | <b>0000000000000914391</b> | Typ silnika           | <b>DIRECT INJECTION</b> |
| Norma emisji spalin     | <b>EURO 5</b>              | Moc silnika           | <b>151KW (205HP)</b>    |



## INFORMACJE O POJEŹDZIE

LICZBA WPISÓW: 49

|  |  |                                       |                              |
|--|--|---------------------------------------|------------------------------|
| Układ kierowniczy                      | <b>LEWOSTRONNY</b>   | Kod skrzyni biegów                    | <b>TF-80SC</b>               |
| Typ skrzyni biegów                     | <b>AUTOMATYCZNA</b>  | Skrzynia biegów                       | <b>AUTOMATIC 6-SPEED AWD</b> |
| Napęd                                  | <b>AWD</b>   | Kod modelu                            | <b>Y381</b>                  |
| Średnie spalanie [l/100km]             | <b>8.12</b> źródło: <a href="http://motostat.pl">motostat.pl</a> | Maksymalna masa zespołu pojazdów [kg] | <b>4500</b>                  |
| Zbiornik [l]                           | <b>70</b>  | Wykończenie wnętrza                   | <b>LEATHER/SSBEI/ESPB/NV</b> |
| Typ licznika                           | <b>KMH</b>   | Kod poziomu wyposażenia               | <b>13</b>                    |
| Kod tapicerki                          | <b>F11600</b>  | Numer seryjny pojazdu                 | <b>106067</b>                |
| Numer seryjny skrzyni biegów           | <b>000000000010K3806483</b>                                      | Fabryka                               | <b>GOTHENBURG</b>            |
| Rynek przeznaczenia                    | <b>POLSKA</b>  | Doładowanie silnika                   | <b>TURBO</b>                 |
| Segment                                | <b>KLASA WYŻSZA-ŚREDNIA</b>                                      | Liczba siedzeń                        | <b>5</b>                     |
| Liczba cylindrów                       | <b>5</b>   | Liczba zaworów                        | <b>20</b>                    |
| Liczba biegów                          | <b>6</b>   | Kraj wytworzenia                      | <b>SZWECJA</b>               |
| Liczba drzwi                           | <b>5</b>   | Ogumienie                             | <b>235/50 R18</b>            |
| Numer homologacji                      | <b>E9*2001/116*0065*11</b>                                       | Moment obrotowy silnika [Nm]          | <b>420</b>                   |
| Maksymalna masa całkowita pojazdu [kg] | <b>2400</b>  | Maksymalny nacisk na oś przednią [kg] | <b>1270</b>                  |
| Maksymalny nacisk na oś tylną [kg]     | <b>1200</b>  |                                       |                              |



## INFORMACJE O PRODUCENCIE

LICZBA WPISÓW: 2

| Nazwa                 | Adres                                  | Kraj    | Data              |
|-----------------------|--|---------|-------------------|
| Volvo Car Corporation | SE-405 31 Goteborg<br>Sweden<br>Sweden | Szwecja | <b>2008-04-04</b> |
| Volvo Car Corporation | SE-405 31 Goteborg<br>Sweden<br>Sweden | Szwecja | <b>1980-04-13</b> |



## BAZA SKRADZIONYCH POJAZDÓW

PRZESZUKANE BAZY: 12 ODNOTOWANO: 0

| Kraj | Źródło   | Znaczenie   | Dostępne informacje |
|------|----------|---|---------------------|
|      | Włochy   | Ewidencja pojazdów skradzionych - Policja   | Nie odnotowano      |
|      | Czechy   | Ewidencja pojazdów skradzionych - Policja   | Nie odnotowano      |
|      | Rumunia  | Ewidencja pojazdów skradzionych - Policja   | Nie odnotowano      |
|      | Litwa    | Ewidencja pojazdów skradzionych - Policja   | Nie odnotowano      |
|      | Słowenia | Ewidencja pojazdów skradzionych - Policja   | Nie odnotowano      |
|      | Holandia | Ewidencja pojazdów skradzionych - Repozytoria Crimimail oraz Stowarzyszenie Ubezpieczycieli | Nie odnotowano      |
|      | Kanada   | Ewidencja pojazdów skradzionych - Policja   | Nie odnotowano      |



## BAZA SKRADZIONYCH POJAZDÓW

PRZESZUKANE BAZY: 12 ODNOTOWANO: 0

| Kraj | Źródło  | Znaczenie | Dostępne informacje |
|------|---|-----------|---------------------|
|      | Słowacja<br>Ewidencja pojazdów skradzionych - Policja                           |           | Nie odnotowano      |
|      | Szwecja<br>Ewidencja pojazdów skradzionych -<br>Stowarzyszenie Ubezpieczycieli  |           | Nie odnotowano      |
|      | Norwegia<br>Ewidencja pojazdów skradzionych - Ettersokt                         |           | Nie odnotowano      |
|      | Kaynine<br>Ewidencja przedmiotów skradzionych - Kaynine<br>(Niemcy)             |           | Nie odnotowano      |
|      | Baza int.<br>Ewidencja pojazdów skradzionych - Niezależne<br>źródła internetowe |           | Nie odnotowano      |



## AKCJE SERWISOWE / USTERKI

LICZBA WPISÓW: 0

| Data | Opis | Źródło | Znaczenie | Komentarz |
|------|------|--------|-----------|-----------|
| --   | --   | --     | --        | --        |

## 2. HISTORIA POJAZDU



### ODCZYTANE PRZEBIEGI

LICZBA WPISÓW: 1

| Data    | Przebieg   | Szczegóły                  |
|---------|------------|----------------------------|
| 2014-07 | 149 475 km | ZGŁOSZONO PRZEBIEG POJAZDU |



### HISTORIA USZKODZEŃ

LICZBA WPISÓW: 3

| Data    | Graficzna prezentacja uszkodzenia | Szczegóły  |
|---------|-----------------------------------|--|
| 2014-08 |                                   | ODNOTOWANO SZKODĘ NA POJEŹDZIE<br>Kraj: <b>POLSKA</b><br>Rezultat: <b>USZKODZENIE NADWOZIA</b><br>Miejsce uszkodzenia: <b>Tył</b><br>Kwota: <b>4500 - 5000 PLN</b> |
| 2014-07 |                                   | ODNOTOWANO SZKODĘ NA POJEŹDZIE<br>Kraj: <b>POLSKA</b><br>Rezultat: <b>USZKODZENIE NADWOZIA</b><br>Miejsce uszkodzenia: <b>Tył</b><br>Kwota: <b>3000 - 3500 PLN</b> |
| 2012-04 |                                   | ODNOTOWANO SZKODĘ NA POJEŹDZIE<br>Kraj: <b>POLSKA</b><br>Kwota: <b>5000 - 7000 PLN</b>   |



### DZIENNIK UŻYTKOWANIA

LICZBA WPISÓW: 0

| Data | Szczegóły |
|------|-----------|
| --   | --        |



### HISTORIA CENOWA

LICZBA WPISÓW: 0

| Data | Cena | Szczegóły |
|------|------|-----------|
| --   | --   | --        |



### CHRONOLOGICZNA HISTORIA POJAZDU

LICZBA WPISÓW: 4

| Data    | Przebieg   | Szczegóły  |
|---------|------------|--|
| 2014-08 |            | ODNOTOWANO SZKODĘ NA POJEŹDZIE<br>Kraj: <b>POLSKA</b><br>Rezultat: <b>USZKODZENIE NADWOZIA</b><br>Miejsce uszkodzenia: <b>Tył</b><br>Kwota: <b>4500 - 5000 PLN</b> |
| 2014-07 | 149 475 km | ZGŁOSZONO PRZEBIEG POJAZDU   |
| 2014-07 |            | ODNOTOWANO SZKODĘ NA POJEŹDZIE<br>Kraj: <b>POLSKA</b><br>Rezultat: <b>USZKODZENIE NADWOZIA</b><br>Miejsce uszkodzenia: <b>Tył</b><br>Kwota: <b>3000 - 3500 PLN</b> |
| 2012-04 |            | ODNOTOWANO SZKODĘ NA POJEŹDZIE<br>Kraj: <b>POLSKA</b><br>Kwota: <b>5000 - 7000 PLN</b>   |

## 3. INFORMACJE DODATKOWE



### DZIENNIK SPRAWDZEŃ

LICZBA WPISÓW: 0

| Data | Rodzaj usługi | IP | Lokalizacja | Znaczenie |
|------|---------------|----|-------------|-----------|
| --   | --            | -- | --          | --        |



### WYPOSAŻENIE

LICZBA WPISÓW: 277

| Kod  | Opis   | Kod  | Opis  |
|------|--|------|---|
| 0002 | wskaźnik temperatury zewnętrznej                       | 0007 | system zabezpieczeń przed urazami kręgosłupa szyjnego (WHIPS) |
| 0012 | układ wspomagania nagłego hamowania (EBA)              | 0028 | sips  |
| 0045 | kluczyk zintegrowany z pilotem centralnego zamka (KIR) | 0049 | system inteligentnego informowania kierowcy (IDIS)            |



## WYPOSAŻENIE

LICZBA WPISÓW: 277

| Kod            | Opis   | Kod            | Opis  |
|----------------|--|----------------|---|
| 0054           | boczne światła obrysowe                                      | 0055           | oświetlenie podłoża w lusterkach zewnętrznych                             |
| 0061           | Clock  | 0062           | obrotomierz   |
| 0064           | podłokietnik pomiędzy przednimi fotelami                     | 0067           | układ ABS   |
| 0068           | trzecie, dodatkowe światło stopu                             | 0071           | układ kontroli stabilności dynamicznej i kontroli trakcji DSTC            |
| 0072           | zaczepy mocowania fotelika dziecięcego ISOFIX                | 0074           | 5 trzypunktowych pasów bezpieczeństwa z napinaczami dla wszystkich miejsc |
| DI06           | sportowa dźwignia zmiany biegów wykończona skórą i aluminium | NC03           | wykończenie wnętrza ALUMINIUM   |
| VP02           | układ wspomaganie parkowania tyłem                           | 000011         | 011 Podgrzewane fotele przednie   |
| 000140         | 140 Alarm Volvo z czujnikami ruchu i przechyłu               | 000179         | 179 Przyciemniane szyby tylne   |
| 000316         | 316 Wykończenie wnętrza CLASSIC WOOD                         | 000334         | 334 Wykończenie dźwigni zmiany biegów skóra/drewno                        |
| 000691         | 691 Układ wspomaganie parkowania przodem i tyłem             | 000750         | 750 Komunikaty w języku polskim   |
| 900202         | 900202 Pakiet "Ciezarowy"                                    | 900378         | 900378 Instrukcja polska  |
| MCF60 / 000114 | Rodzinny: 114 Elektryczna blokada otwarcia drzwi tylnych     | MCF60 / 000322 | Rodzinny: 322 Dwustopniowe podwyższenia siedzisk tylnej kanapy            |
| 0111           | COMMON 98: Y285/Y286/Y381/Y483                               | 0201           | COMMON MATERIAL: Common material - all type 98 cars                       |
| 1067           | INTERIOR CODE: Leather, Sandstone Beige/Espresso Brown       | 1202           | EXTERIOR PAINT,TYPE: Metallic   |
| 1500           | STOLEN VEHICLE TRACKING: N.A variant family 15               | 2601           | ENGINE OPTIMIZATION AFTERMARKE: Standard calibration engine               |
| 2H01           | CALLSTART OF PARKING HEATER: W/o callstart of parking heater | 2L01           | PART NUMBER FORMAT: KDP Format  |
| 2Q01           | IDIS: Intelligent Driver Information System 1                | 2T01           | IGNITIONLOCK: Start Control Unit  |
| 4101           | FMVSS-DECAL/PLATE: W/o FMVSS decal/sign                      | 4403           | CHILDSEAT DECAL: Child seat decal, eng decal/sign                         |
| 4802           | OIL QUALITY: Std. oil  | 4901           | PARTS FOR TAXI: Parts excluded for TAXI                                   |
| 4X19           | MARKET CODE: Market variant, not for part steering           | 5001           | PARTS FOR SPECIAL VEHICLES: Parts excluded for Special Vehicle Executives |
| 5101           | ADM FOR S-CAR (UNIQUE PNO): Adm. variant for standard car    | 5202           | ADM POLICE/TAXI: Administrative designation for not police cars           |
| 5601           | BIGGER BATTERY: Standard battery                             | 6702           | ADM. FAMILY FOR RTI-FUNCTION: With RTI-function                           |
| 7602           | SWITCH BLOCK PANEL, 6 IN ROW: 1 cover panel                  | 7902           | TOTAL WEIGHT CHECK: Carweight is OK                                       |
| 8B02           | GEARBOX/DRIVELINE: 6-speed automatic, 2WD and 4WD            | 8D04           | OUTER REAR VIEW MIRRORS: Outer rear view mirror package                   |
| 8H01           | SEAT PADDING: SEAT PADDING 1                                 | 8I0C           | CAR/GEARBOX/DRIVELINE: XC70 auto 4wd                                      |



## WYPOSAŻENIE

LICZBA WPISÓW: 277

| Kod  | Opis  | Kod  | Opis   |
|------|---|------|--|
| 8K0F | CAR/GEARBOX/DRIVELINE/EMISS: XC70 auto 4wd EMISSG                         | 9302 | INFOTAINMENT GROUND CABLE: Ground for Infotainment cable               |
| 9V02 | FAMILY FOR COLOUR CHANGE: Adm variant without colour change               | AA04 | VEHICLE TYPE X: Y381 XC70'   |
| AC01 | BRAND: Volvo  | AF02 | DOORS: 5 door  |
| AG02 | TRANSMISSION: AWD All wheel drive   | AP05 | SALES VERSION - ADMINISTRATIVE: Sales version 13, Trim level 3         |
| C101 | STEERING WHEEL POSITION: Left Hand Drive                                  | C302 | MAIN MARKET: Europe and Overseas markets                               |
| C402 | MAIN MARKET, PLATES AND LABELS: Labels outside NORDIC markets             | CB07 | ENGINE DYNAMICS/ STC: 5-cyl turbo engine, diesel                       |
| CD01 | BIFUEL: Not Bifuel  | CE08 | ENGINE FAMILY: D5244TX   |
| CF48 | ENGINE: 5CYL/2.4L/4V D5244T 205PS/420Nm 151kW 2,400L                      | CG02 | FUEL: Diesel   |
| CH02 | CYLINDERS ENGINE PETROL/DIESEL: 5-cylinder engine                         | CJ01 | FLEXIFUEL: No flexifuel  |
| CL02 | TURBO CHARGING: Turbo engine  | CR02 | ALTERNATOR: Alternator 180A  |
| CS03 | BATTERY: T7 80Ah 700 Cold Cranking Ampere                                 | CU03 | OIL LEVEL SENSOR: Oil level sensor and Static Measurement              |
| CX02 | BATTERY MONITOR SENSOR: Battery Monitor Sensor                            | CZ01 | BATTERY MARKETS: no reduced post                                       |
| DB04 | GEARBOX: Automatic 6-speed AWD  | DC02 | NEUTRAL CONTROL AUTO.GEAR: With NEUTRAL CONTROL function               |
| DD03 | PEDAL ARRANGEMENT: Pedal standard   | DF02 | GEARBOX,TYPE: Automatic gearbox  |
| DI03 | GEARLEVER,TYPE/KNOB: Gearlever knob leather with wood inlay               | DR01 | ENGINE COOLING FAN PERFORMANCE: Fan high performance                   |
| E102 | DAMP SENSOR: Damp sensor  | E203 | SUN SENSOR: Dual zone sun sensor                                       |
| EA02 | PTC HEATER (SUPL. AIR HEATER): Positive Thermal Coefficient, 1200W        | ED01 | CLIMAT CONTROL UNIT: Electronic Climat Control                         |
| EE02 | GRADUATION CLIMAT CONTROL: Graduation Celcius                             | EF03 | REAR BELT DETECTION: Rear belt detection, left, right & middle belts   |
| EG03 | FRONT ACTIVE SEAT BELT: Passive Front Seat Belts (Retractor Pretensioner) | EI02 | LAP BELT PRETENSIONER: Lap Belt Pretensioner Driver Seat               |
| EJ02 | CUTOFF SWITCH PASSENGER AIRBAG: Cut-Off Switch Passenger AirBag           | EK01 | FRONT CRASH SENSING SYSTEM: Front Crash Sensing System, Upfront Sensor |
| EL02 | SAFETY BELT: EU/OS type   | EM01 | AIRBAG TYPE: Airbag 2 step   |
| EO02 | AIRBAG, PACKAGE: 2 step airbag, drivers/passenger side                    | EP02 | PASSENGER AIRBAG: Passenger airbag                                     |
| EU01 | CLIMATE CONTROLE STYLE: Controle swich with Chrome ring                   | EV02 | ROOF HATCH: No roof hatch  |
| EY03 | GLOBAL OPEN/CLOSE: Global open/close doors+sunroof                        | F101 | COLOUR PACKAGE, INTERIOR: Package for colour matching, interior        |
| F201 | COLOUR PACKAGE, EXTERIOR: Package for colour matching, exterior           | FL02 | BASE COLOUR INTERIOR: Sandstone Base Colour Interior                   |



## WYPOSAŻENIE

LICZBA WPISÓW: 277

| Kod  | Opis   | Kod  | Opis  |
|------|--|------|---|
| FN01 | COLOUR MATCHING DRIVING UNIT: Standard colour steering wheel and IP-top, SAND interior               | FT01 | LANE KEEPING AID: Less Lane Keeping Aid                                     |
| G303 | FUEL PUMP: Diesel fuel pump  | G501 | FUEL FILLER PIPE: Large fuel filler pipe, leaded fuel                       |
| G601 | FUEL TANK, VOLUME: Volume 70 Litre   | GB02 | DIAGNOS SYSTEM: EOBD  |
| GC02 | FUEL PIPE TYPE: Fuel pipe type 2   | GK02 | EMISSIONS VERSION: Emissions version STAGE5, VIN pos8=5:Use GN after 08w20  |
| GN03 | VERSION DIVIDER FOR VIN: Version Divider, VIN pos8 = 5   | GR01 | GRILL TYPE: Grill, std  |
| J902 | ADVANCED FRONT LIGHTNING: Advanced Front Lightning   | JA03 | HEADLIGHTS,SYMMETRY: RH asymmetry   |
| JB06 | HEADLIGHTS, TYPE: Advanced Front lightning system with auto adj/ Menu controlled/ Mech or no Tourist | JC02 | DAYRUNNING LIGHT: Standard dipped headlight (Only light in pos 2)           |
| JD02 | FOGLIGHT FUNCTION: Foglight without restrictions   | JG04 | HEADLIGHT CLEANING: Headlight washer, low flow                              |
| JH02 | HORN: Horn, std.   | JJ02 | THEFT PROTECTION COVER: With theft protection cover                         |
| JK02 | THEFT PROTECTION COVER, REAR: Theft protection cover, rear   | JS01 | REAR FOGLIGHT TOWFUNCTION: Foglights running even when trailer is connected |
| JT02 | FOGLIGHTS IN SPOILER: Foglight   | JZ01 | RADIO SOUND: Standard Radio Sound   |
| K104 | AUDIOPAYER: Player for 1 CD with MP3   | K302 | AUDIO AUXILIARY INPUT: Auxiliary audio input                                |
| K503 | RADIO, AMP & SPEAKER SYSTEM: Audio 'High Performance' 4*40W, 8 speakers                              | K702 | REAR VIEW MIRRORS, OUTER: Electric retractable mirrors                      |
| K802 | MEMORY FUNCTION: With memory   | KA03 | SPEED LIMITATION: Speed limit 210 km/h                                      |
| KB04 | COMBINED INSTRUMENT: KM/H for EU with watch dial   | KE02 | TRIP COMPUTER: With Trip Computer   |
| KG02 | CRUISE CONTROL: Cruise control   | KJ10 | SAFETY BELT REMINDER: EU type, all seats gen.4 logic                        |
| KK07 | ACCESSORY USB UNIT: USB & IPOD function in IAM   | KQ02 | MICROPHONE: Microphone  |
| KT01 | VIDEO ALLOWED: Local Config Controll   | KX04 | HOLE RTI/TV/AUDIO ,DASH: RTI/TV/AUDIO hole, Dash                            |
| L102 | ALARM: Alarm   | L202 | CENTRAL LOCK, TYPE: Blocked lock mode                                       |
| L303 | CHILD LOCK.REAR DOORS: Electrical child lock, rear side doors  | L501 | PASSIVE ALARM ACTIVATION: W/o automatic alarm activate                      |
| L705 | SELF OPENING BOOTLID/TAILGATE: Self opening Tailgate (With Release Motor)                            | L802 | LEVEL SENSOR - IF ALARM: With level sensor                                  |
| LC02 | DRIVE AWAY RELEASE: Drive Away Release   | LD01 | REAR VIEW MIRROR,LH SIDE: LH side rear view mirror, wide angle              |
| LE02 | REAR VIEW MIRROR, RH SIDE: RH side mirror, wide angle, without text                                  | LF02 | REAR VIEW MIRROR, COLOUR MATCH: Colour matched rear view mirrors            |
| LG02 | REAR VIEW MIRROR HOUSING TYPE: Rear view mirror housing large  | LK02 | PUDDLE LIGHT, OUTER MIRRORS: With puddle light                              |
| LM01 | UNLOCK SETTING: One step opening   | LO02 | PANIC ALARM: Panic alarm  |





## WYPOSAŻENIE

LICZBA WPISÓW: 277

| Kod  | Opis   | Kod  | Opis  |
|------|--|------|---|
| LR02 | DARKENED REAR WINDOWS: Dark glasses, rear sidedoor and cargo area  | LT02 | OPEN, REAR SIDE DOOR: 2 pull to open Rear side door, from locked                                      |
| LV02 | INTERIOR MOTION SENSOR: Interior movement sensor                   | LX04 | REAR WIEW MIRROR - GLASS: LH mirror: Wide, RH mirror: Wide  |
| LY24 | FREQUENCY - REMOTE CONTROLS: Frequency 434 MHZ                     | LZ04 | LOCK STATUS INDICATION CONFIG: Mechanical Lock Status Indication                                      |
| MC02 | COUPE FILTER: Air Quality System                                   | MI02 | ACKNOWL. SIGNAL LOCK/ALARM: Lock/unlock acknowledge   |
| MK01 | SPEECH CONTROL LANGUAGE: Speech Control Language VOICE, US English | MN01 | FREQUENCY BAND & STEP,RADIO: Frequency band and step for EU   |
| MO19 | LANGUAGE: POLISH for instrument and radio                          | MR02 | POWER WINDOWS: DCU Power Side Windows   |
| MS0B | INSTRUCTIONS: Owners manual Polish                                 | MT05 | INSTRUMENT CLUSTER CALIBR.: Parameter file for EUROPE   |
| MU01 | SERVICE INTERVAL: User Defined Serviceinterval                     | MV0D | SERVICE DISTANCE: Service distance, 30000 km.   |
| MW03 | SERVICE TIME: Service time, 12 months.                             | MX0D | SERVICE ENGINE TIME: Service Engine Time, 650 hour  |
| N102 | LUGGAGE NET, STEEL: Steelnet                                       | N302 | LOAD RETAINER LUGGAGE: Load retainer luggage  |
| N403 | LOADHOLDER: Loadholder,5-door                                      | N502 | ARMREST/MIDDLE REAR SEAT: Centre armrest with cupholder   |
| N802 | ATTACHM CHILDSEAT FRONT: Child seat attachment                     | N902 | CHILD SEATS REAR,OUTER: With outer childseats   |
| NB02 | UNI DECOR INTERIOR: Uni decor, Mannekin, air vents, CCM knobs      | NC04 | INTERIOR DECOR PANELS: Decor wood 'CLASSIC'   |
| NE02 | PARKINGBRAKE, TYPE: Electrical parking brake                       | NG02 | UPHOLSTERY MATERIAL: Standard Leather Comfort   |
| NI02 | DRIVERS SEAT: El adjustable drivers seat                           | NJ05 | PASSENGERS SEAT: Mech adjustable passengers seat 4 way - with foldable backrest From 13w20 see fam.P2 |
| NL16 | SEAT HEAT CALIBRATION: Lowtemp 36C - Hightemp 43C                  | NM02 | HEATED FRONT SEATS: Heated front seats  |
| NO02 | HEADRESTS REAR, FOLDING: El folding rear headrests                 | NP01 | SEATS: 5seat  |
| NR02 | END STOP FRONT SEAT, LEFT: End stop front seat, Left side          | NY02 | PROTECTION CARPETS COUPE: Carpet kit  |
| P901 | WHEEL DIRT DEFLECTOR: No Dirt Deflector                            | PB02 | MAKEUP LAMP SUNVISOR: 2 illuminated sun visors  |
| PE02 | 12 VOLT OUTLET LUGGAGE: 12V outlet in luggage                      | PI03 | FIRST AID KIT: Aidkit type 2/ DIN 13164   |
| PK02 | LOADCOVER,5-DOOR: Load cover, soft, 5-door                         | PN02 | REAR VIEW MIRROR,TYPE: Automatic dimming inner  |
| PT00 | TOWBAR FIXED (adm family): fictious variant                        | PW01 | STEERING GEAR C-FACTOR: Standard steering C-factor  |
| PY03 | TYRE SIZE: Tyre, 18 inch   | PZ04 | TYRE DIM: Tyre Dimension 235  |
| R001 | WHEEL MATERIAL: Aluminium Wheel                                    | R111 | WHEEL: A 18' 7.5X18X55 EH2  |



## WYPOSAŻENIE

LICZBA WPISÓW: 277

| Kod  | Opis   | Kod  | Opis  |
|------|--|------|---|
| R304 | WHEEL, INCH: 18' Wheel   | R414 | TYRE BRAND: Pirelli   |
| R543 | TYRE DIMENSION: 235/50R18 V  | R605 | SPARE WHEEL: Repair kit, ver 2  |
| R927 | TYRE CIRCUMFERENCE: Rolling circumference 2110mm                                     | RA01 | CHASSIE TYPE: Chassi 1, COMFORT / TOURING   |
| RC02 | BRAKE PADS: Standard pad   | RD01 | HILL LAUNCH ASSIST: No Hill Launch Assist   |
| RE03 | WHEEL BRAKES TYPE FRONT: Brake discs 16,5 FNR  | RJ03 | EL.VACUMPUMP, REAR BOOSTER: Mechanical vacuum pump                                    |
| RK04 | WHEEL BRAKES TYPE REAR: Big EPB (Electrical Parking Brake) calliper, ventilated disc | RN02 | HILL DESCENT CONTROL: Hill Descent Control  |
| RO03 | STEERING WHEEL COLOUR: Standard colour steering wheel                                | RS02 | EMERGENCY BRAKE LIGHT: Emergency Brake Light, flashing                                |
| RU06 | STEERING WHEEL: Leather steering wheel, with Decor inlays                            | RV02 | AUDIO BUTTONS, STEERING WHEEL: Audio buttons in steeringwheel                         |
| RY04 | VIBR. DAMPER STEERING WHEEL: Vibration damper, 5cyl                                  | RZ02 | POWERSTEERING TYPE: Electro hydraulic power steering                                  |
| SA02 | BLUETOOTH HANDSFREE: Bluetooth handsfree   | SF02 | AIR INTAKE FRONT: Air intake without snowflap   |
| SH01 | SUNGLASS HOLDER: No sun glass holder   | SI02 | WHEEL SPEED SENSOR TYPE: Wheel speed sensor without direction recognition             |
| SL02 | STEERING COLUMN LOCK: Steering Column Lock   | SR02 | TAILPIPE: Double Pipes, 2 brackets, Visible   |
| T004 | EMBLEM,REAR,LH-SIDE: XC70 emblem left side   | T104 | EMBLEM,REAR: AWD emblem tailgate  |
| T209 | COMPLEMENTARY EMBLEM,REAR: Emblem 'D5'   | T304 | DECAL TRIMLEVEL: Summum Trim level 3  |
| T501 | PLENUM COVER/NOISE INSULATION: No Plenum cover/ Noise insulation                     | T601 | SIDE WINDOWS: Tempered side windows, without WRG                                      |
| T702 | RAINSENSOR: Rain sensor  | T801 | WINDSCREEN: Standard Windscreen Glass   |
| TA01 | HEATED WINDSCREEN: No Heated Frontscreen   | TB02 | WINDSCREEN WASHER NOZZLES: Heated windscreen washer nozzles                           |
| TD01 | CHROME FRONT: Standard Front   | TE01 | COLOURED LOWER EXTERIOR: Standard lower area  |
| TH01 | BUMPER, TYPE: Bumper type 1  | TI02 | SKIDPLATE: Skidplate Coated   |
| TL01 | TREAD PLATE: Tread plate, standard   | TM02 | DECOR SIDE WINDOWS: Bright decor side windows, upper + lower, high gloss mirror foot. |
| TP02 | ROOFRAILS: Roofrails   | TR01 | DOOR MOULDING LOWER: Door Moulding Lower  |
| TS02 | WARNING TRIANGLE: Triangle   | TZ02 | CENTERSTACK KROM: Chrome centerstack  |
| US01 | UNIT SETTINGS: Temp:C, Clock:24, Distance:KM, Fuel:Liter/KM                          | V102 | PARKING TICKET HOLDER: With Ticket holder   |
| VA02 | NAVIGATION SYSTEM: Navigation system for EU  | VB02 | DVD DISC FOR RTI: DVD disc, Europe  |



## WYPOSAŻENIE

LICZBA WPISÓW: 277

| Kod  | Opis  | Kod  | Opis   |
|------|---|------|--|
| VC01 | REFRIGERATOR: Witout Refrigerator                           | VI02 | TRAFFIC INFORMATION: With Traffic Message Channel, TMC                                     |
| VM02 | INFOTAINMENT THEFT PROTECTION: InfotainmentTheft protection | VP03 | PARKING ASSISTANCE: Parking assistance, rear and front                                     |
| VQ04 | PAM SCAN PATTERN: Pattern 4 (VCC Standard)                  | VX02 | CEM: Middel spec CEM   |
| XB0A | PACKAGES FOR PLATES AND DECALS: Labels for MC19             | XD01 | USER PACKAGES: User package  |
| XT10 | MODEL/VEHICLE LINE FOR TREAD: ONLY FOR TREAD!               | Y802 | VIN POS 4 or 7: VIN-code position 4  |
| Y906 | VIN POS 5 or 8: VIN-code position 5                         | YA03 | VEHICLE INSPECTION NUMBER: YV1   |
| YB06 | YEAR DESIGNATION LETTER: Year des B = model year 2011       | YC13 | MAX FRONT AXLE WEIGHT: 1270 kg   |
| YD13 | MAX REAR AXLE WEIGHT: 1200 kg                               | YE20 | GROSS WEIGHT: 2400 kg  |
| YF23 | TRAIN WEIGHT: 4500 kg                                       | YG00 | MAXIMUM LOAD: Not applicable variant   |
| YJ04 | TYRE PRESSURE SPARE WHEEL: - The sign '-' to be printed.    | YN00 | MAXIMUM TOWING WEIGHT: No weight   |
| YP16 | WVTA-NUMBER: e9*2001/116*0065*11                            | YT14 | TYRE INFLATION PRESSURE LIGHT: R:230(33) F:230(33) R:260(38) F:260(38) R:240(35) F:240(35) |
| YV01 | OCCUPANTS: No occupants                                     | YX05 | TYRE INFLATION PRESSURE HEAVY: Tyre inflation pressure                                     |
| YY01 | TYRE DIMENSION FOR LABELS: NONE                             | --   |  |



## ARCHIWALNE ZDJĘCIA POJAZDU

LICZBA ZDJĘĆ: 0

| Data | Szczegóły | Liczba zdjęć |
|------|-----------|--------------|
| --   | --        | --           |

### Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez ASDIRECT Sp. z o.o. o tym fakcie. ASDIRECT Sp. z o.o. nie ponosi odpowiedzialności za treść danych zawartych w Raportach. Treść taka może być niepełna lub niezgodna ze stanem rzeczywistym.

Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi ASDIRECT Sp. z o.o. Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego.

Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody ASDIRECT Sp. z o.o.

ASDIRECT Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiegokolwiek formie.

ASDIRECT Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez ASDIRECT Sp. z o.o. w jakiegokolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.