

VIN: **WVWZZZ1KZAM653564**

Marka: **VOLKSWAGEN**

Model: **GOLF 1.6 TDI**

Typ paliwa: **DIESEL**

Rodzaj nadwozia: **KOMBI**

Data wygenerowania raportu: 2019-03-30 00:26:24 UTC +0100



## WIEK POJAZDU

WG DATY PRODUKCJI / ROKU MODELOWEGO

WG PIERWSZEJ REJESTRACJI POJAZDU



lat(a)



mies.



lat(a)



mies.

Data produkcji / Rok modelowy: **2010-01-30**

Data pierwszej rejestracji: -



## PODSUMOWANIE RAPORTU

### 1. INFORMACJE PODSTAWOWE

Przydatne informacje

Liczba wpisów: 2



Informacje o pojeździe

Liczba wpisów: 39



Informacje o producencie

Liczba wpisów: 1



Poprawność VIN

Niedostępny



Sprawdzenie baz skradzionych pojazdów

Przeszukane bazy: 12, Odnotowano: 0



Akcje serwisowe / usterki

Liczba wpisów: 0



### 2. HISTORIA POJAZDU

Odczytane przebiegi

Liczba wpisów: 1



Historia uszkodzeń

Liczba wpisów: 6



Dziennik użytkowania

Liczba wpisów: 0



Historia cenowa

Liczba wpisów: 1



### 3. INFORMACJE DODATKOWE

Dziennik sprawdzeń

Liczba wpisów: 0



Archiwalne zdjęcia pojazdu

Liczba wpisów: 11



Wyposażenie

Liczba wpisów: 192



# 1. INFORMACJE PODSTAWOWE




## PRZYDATNE INFORMACJE

### ŚREDNI PRZEBIEG POJAZDU

156756

**Uwaga:** Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

### ŚREDNI PRZEBIEG POJAZDÓW



**Uwaga:** Na wykresie przedstawiono średni przebieg wg rocznika samochodów z silnikiem PB i ON.



## INFORMACJE O POJEŹDZIE

LICZBA WPISÓW: 39

VIN: **WVWZZZ1KZAM653564**



Producent	<b>VOLKSWAGEN</b>	Model	<b>GOLF</b>
Rodzaj nadwozia	<b>KOMBI</b>	Typ paliwa	<b>DIESEL</b>
Pojemność silnika [cm3]	<b>1598</b>	Kraj producenta	<b>NIEMCY</b>
Rok modelowy	<b>2010</b>	Kod koloru lakieru	<b>8E / A7W</b>
Kolor lakieru	<b>REFLEX SILVER METALLIC</b>	Próbka koloru lakieru	
Kod koloru wnętrza	<b>XT</b>	Kolor wnętrza	<b>BLACK</b>
Data produkcji	<b>2010-01-30</b>	Kod silnika	<b>CAYC</b>
Silnik	<b>1.6 TDI</b>	Norma emisji spalin	<b>EURO 5</b>
Typ silnika	<b>DIRECT INJECTION</b>	Moc silnika	<b>77KW (105HP)</b>



## INFORMACJE O POJEŹDZIE

LICZBA WPISÓW: 39

Układ kierowniczy	<b>LEWOSTRONNY</b>	Kod skrzyni biegów	<b>LHW</b>
Typ skrzyni biegów	<b>MANUALNA</b>	Skrzynia biegów	<b>5-SPEED MANUAL TRANSMISSION</b>
Kod modelu	<b>AJ542K</b>	Poziom wyposażenia	<b>SPORTS</b>
Średnica cylindra [mm]	<b>79.50</b>	Kod napędu	<b>5S</b>
Skok tłoka [mm]	<b>80.50</b>	Kod poziomu wyposażenia	<b>A8F</b>
Fabryka	<b>PUEBLA</b>	Rynek przeznaczenia	<b>POLSKA</b>
Układ cylindrów	<b>R - RZĘDOWY</b>	Doładowanie silnika	<b>TURBO</b>
Typ układu rozrządu	<b>DOHC</b>	Segment	<b>AUTA KOMPAKTOWE / KLASA NIŻSZA-ŚREDNIA</b>
Liczba cylindrów	<b>4</b>	Liczba zaworów	<b>16</b>
Liczba biegów	<b>5</b>	Kraj wytworzenia	<b>MEKSYK</b>
Średnie spalanie [l/100km]	<b>6.01</b> źródło: <a href="http://motostat.pl">motostat.pl</a>		



## INFORMACJE O PRODUCENCIE

LICZBA WPISÓW: 1

Nazwa	Adres	Kraj	Data
Volkswagen AG	Wolfsburg/Hannover Wolfsburg/Hannover Germany	Niemcy	<b>2001-10-07</b>



## BAZA SKRADZIONYCH POJAZDÓW

PRZESZUKANE BAZY: 12 ODNOTOWANO: 0

Kraj	Źródło	Znaczenie	Dostępne informacje
	Włochy	Ewidencja pojazdów skradzionych - Policja	✓ Nie odnotowano
	Czechy	Ewidencja pojazdów skradzionych - Policja	✓ Nie odnotowano
	Rumunia	Ewidencja pojazdów skradzionych - Policja	✓ Nie odnotowano
	Litwa	Ewidencja pojazdów skradzionych - Policja	✓ Nie odnotowano
	Słowenia	Ewidencja pojazdów skradzionych - Policja	✓ Nie odnotowano
	Holandia	Ewidencja pojazdów skradzionych - Repozytoria Crimimail oraz Stowarzyszenie Ubezpieczycieli	✓ Nie odnotowano
	Kanada	Ewidencja pojazdów skradzionych - Policja	✓ Nie odnotowano
	Słowacja	Ewidencja pojazdów skradzionych - Policja	✓ Nie odnotowano
	Szwecja	Ewidencja pojazdów skradzionych - Stowarzyszenie Ubezpieczycieli	✓ Nie odnotowano
	Norwegia	Ewidencja pojazdów skradzionych - Ettersokt	✓ Nie odnotowano
	Kaynine	Ewidencja przedmiotów skradzionych - Kaynine (Niemcy)	✓ Nie odnotowano
	Baza int.	Ewidencja pojazdów skradzionych - Niezależne źródła internetowe	✓ Nie odnotowano



## AKCJE SERWISOWE / USTERKI

LICZBA WPISÓW: 0

Data	Opis	Źródło	Znaczenie	Komentarz
--	--	--	--	--

## 2. HISTORIA POJAZDU



### ODCZYTANE PRZEBIEGI

LICZBA WPISÓW: 1


Data	Przebieg	Szczegóły
2015-03-10	77 000 km	ZGŁOSZONO PRZEBIEG POJAZDU



### HISTORIA USZKODZEŃ

LICZBA WPISÓW: 6

Data	Graficzna prezentacja uszkodzenia	Szczegóły
2017-08		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Kwota: <b>1000 - 1250 PLN</b>
2015-03		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Tył, Lewy tył, Prawy tył</b> Kwota: <b>1500 - 2000 PLN</b>
2015-02		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Tył, Lewy tył, Prawy tył</b> Kwota: <b>4500 - 5000 PLN</b>
2014-06		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Przód, Prawy przód</b> Kwota: <b>1500 - 2000 PLN</b>
2014-05		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE SZYB, USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Przód, Przednia szyba</b> Kwota: <b>1500 - 2000 PLN</b>

 USZKODZENIE SZYB



## HISTORIA USZKODZEŃ

LICZBA WPISÓW: 6

Data	Graficzna prezentacja uszkodzenia	Szczegóły
2012-01		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Kwota: <b>1500 - 2000 PLN</b>



## DZIENNIK UŻYTKOWANIA

LICZBA WPISÓW: 0

Data	Szczegóły
--	--



## HISTORIA CENOWA

LICZBA WPISÓW: 1

Data	Cena	Szczegóły
2015-03-10	<b>35 900 PLN brutto</b>	ODNOTOWANO CENĘ / WARTOŚĆ



## CHRONOLOGICZNA HISTORIA POJAZDU

LICZBA WPISÓW: 8

Data	Przebieg	Szczegóły
2017-08		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Kwota: <b>1000 - 1250 PLN</b>
2015-03		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Tył, Lewy tył, Prawy tył</b> Kwota: <b>1500 - 2000 PLN</b>
2015-03-10	77 000 km	ZGŁOSZONO PRZEBIEG POJAZDU
2015-03-10		ODNOTOWANO CENĘ / WARTOŚĆ <b>35 900 PLN brutto</b>
2015-02		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Tył, Lewy tył, Prawy tył</b> Kwota: <b>4500 - 5000 PLN</b>
2014-06		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Przód, Prawy przód</b> Kwota: <b>1500 - 2000 PLN</b>
2014-05		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Rezultat: <b>USZKODZENIE SZYB, USZKODZENIE NADWOZIA</b> Miejsce uszkodzenia: <b>Przód, Przednia szyba</b> Kwota: <b>1500 - 2000 PLN</b>
2012-01		ODNOTOWANO SZKODĘ NA POJEŹDZIE Kraj: <b>POLSKA</b> Kwota: <b>1500 - 2000 PLN</b>

### 3. INFORMACJE DODATKOWE



#### DZIENNIK SPRAWDZEŃ

LICZBA WPISÓW: 0

Data	Rodzaj usługi	IP	Lokalizacja	Znaczenie
--	--	--	--	--



#### WYPOSAŻENIE

LICZBA WPISÓW: 192

Kod	Opis	Kod	Opis
E0A	Special editions: Without special action equipment	1PF	Lockable wheel bolts: Standard wheel bolts
0HM	Vehicle class differentiation units/platform components: Vehicle class differentiation -1KM- Build status corresponds to production in Mexico	0P7	tail pipe: Rear side exhaust tailpipe
UG0	drive-off assistance: Without hill start assist/hill descent control/comfort driving assist	7MG	Emission standard: Emission standard EU5
1D0	Trailer hitch: without trailer towing	4UF	airbag: Airbag for driver and front passenger with front passenger airbag deactivation
1E0	Aktivkohlebehälter / Ottopartikelfilter: Without activated charcoal canister	8ZH	Aerials: Antenna for AM/FM reception, "diversity"
6XG	Exterior mirror setting: Exterior mirrors with memory feature, power-adjustable/heated	5SL	Left exterior mirror: Left exterior mirror, aspherical
5RQ	Right exterior mirror: Right exterior mirror: convex	1X0	Drive type: Front-wheel drive
9WL	"Multimedia"video/DVD/notebook connection: Jack for external audio source	A8F	Equipment levels: Sports equipment
1KS	Brake type in rear: Disc brakes in rear (Geomet D)	J0N	batteries: Battery 330 A (61 Ah)
1ZM	Brake type, front: Disc brakes in front (Geomet D)	6FF	Components with special surface: Exterior mirror housing and various attachments colour coded to vehicle
NY0	Battery/alternator capacity: Standard battery/alternator capacity	B0A	Component part sets with country-specific design requirements: build parts set without county specific documentatio
1S1	vehicle tools and jack: vehicle tools and jack	1AT	Brake systems: Electronic stability control (ESC)
0VT	Owner's manuals: Information kit in Polish	9Z0	Operating voltage: Operating voltage 12 V
9U1	brake wear indicator: brake wear indicator	9T1	Heated washer nozzles: Heated washer nozzles in front
7QA	CD ROM/DVD/SD card: Without CD/DVD for navigation	7A0	CD changer/CD player: Without CD changer/CD player
2H0	"Charism": Without "drive select"	QJ3	Chrome package: Chrome package (version 2)



## WYPOSAŻENIE

LICZBA WPISÓW: 192

Kod	Opis	Kod	Opis
C17	General operating permit, alterations: Operating permit, alteration	3S2	Roof rails/roof load rack: Black roof rails
3FA	Roof insert/convertible top: roof without cut out	1JA	Suspension system in rear: Rear shock absorption, basic design 1
G67	Suspension system in front: Shock absorption in front	3X0	Load-through hatch/ski bag: without load through system
2G5	Insert for the filling up of unleaded fuel/fuel type: Filler neck module 1 without insert	0EJ	Installation differentiation for components: Installation differentiation for transmission MQ 250 -- vehicle components --
7AS	Theft protection system: Anti-theft alarm system, interior monitoring, backup horn and towing protection	5MJ	Inserts: Decorative inserts
7M5	Scuff plates: Without impact protection film for door sill	7X5	Park distance control: Park assist
UF0	Electric interface for external use: Without electric interface	0FL	Manufacturing sequence differentiation: Mexico manufacturing sequence
4R4	window regulator: Power windows with comfort operation and circuit breaker	6A0	fire extinguisher: without fire extinguisher
VL0	Pedestrian protection: Standard pedestrian protection measures	VF0	Pedal cluster: Standard pedal cluster
8K1	Headlight activation: Separate daytime running light	F0A	Vehicle specifications: No special purpose vehicle, standard equipment
8GU	Alternators: Alternator 140 A	0YG	Weight category rear axle: Weight range 7 installation control only, no requirement forecast
L07	Weight category front axle: Suspension range 07 installation control only, no requirement forecast	TF3	Base engine: 4-cylinder diesel engine 1.6 l unit 03L.1
4U5	Luggage netting/pocket on backrest(s): Luggage pockets on backrest	3U2	Luggage compartment cover: Sliding trunk cover
8T2	cruise control system: Electronic cruise control system (CCS)	VC0	Garage door opener: without Garage door opener
5A2	Luggage compartment trim: Comfort luggage compartment trim	G0C	Transmission specifications: 5-speed manual transmission
3P1	Brackets: Bracket for first aid kit and warning triangle	6PC	handle for hand brake lever: handbrake lever grip (leather)
5J0	Rear spoiler: Without rear spoiler	8M1	Rear window wiper and washer system: Rear window wiper washer system with intermittent wipe
3NW	Rear seats: Rear seat bench/backrest, split folding with center armrest	9AK	Heating and air-conditioning system: Climatronic with impact pressure control, CFC-free
8BG	Headlamps: Twin-headlamps for driving on the right, with integrated high beam	FC0	Customized installation: Without individual installation
6T0	Interior light in footwell: Without interior light in footwell	U5A	Instrument clusters: Instrument insert, km/h speedometer
4L2	Breakaway interior rearview mirror: Breakaway interior rearview mirror, dimming	0KA	Sticker (customized or special edition): Without decals and emblems



## WYPOSAŻENIE

LICZBA WPISÓW: 192

Kod	Opis	Kod	Opis
K8D	Body style: Wagon/Avant	4W0	Cassette and CD storage unit: without cassette / CD tray
1W2	coolbox: Glove compartment cooling system	4H3	child safety: Manual child lock
QS0	Electronic map cooling system: Without electronic map cooling system	QA0	Child seats: without child seat
0Y1	Climatic zones: Standard climatic zones	QR0	Compass/road sign display: Without compass/road sign display/ dynamic road sign display
3T2	headrest for seat, rear: Three rear head restraints	3J1	Head restraints: Hight-adjustable head restraints for front seats
2LD	Fuel tank treatment: Fuel tank without differentiation of special material treatment (fluorination/co-extrusion)	1Z0	Fuel quantity for initial filling: Initial standard fuel filling
0F3	Fuel systems: Fuel system for diesel engine	5C0	Body measures: Without special body measures
3G0	Child seat anchors in front: Without child seat anchora in front (ISOFIX)	6KC	Radiator grille: Radiator grille
6P1	Rear license plate bracket: Rear license plate carrier (ECE)	6W1	Front license plate bracket: Front license plate carrier (large)
5K5	Paint preservative/transit coating: Transport protection film with additional transport protection measures	FB0	Paint coating: standard paint coating
3GD	Rear cargo area: Plane rear cargo area	L0L	Steering system arrangement: Left-hand drive
8S4	Reading lamp: Two reading lights front, two rear	1N3	steering: Speed-related variable steering assist (Servotronic)
3H0	Backrest release: Without backrest release for front seats	VK0	Air duct, front area: Air duct, standard
2P1	Load edge protection: Plastic loading edge protection	7P4	Lumbar support: Manually adjustable lumbar support in front seats
2PP	steering wheels: Leather-wrapped multi-function steering wheel	8RM	Speaker installation: 8 speakers (passive)
8Q4	Headlight range control: Headlight range control with cornering light	6E3	Center armrest: Center armrest in front
UM0	Marten repeller: Without marten repeller	9Q5	Multi-function display/trip computer: Multi-function display with control
8Z5	Engine cooling: not hot country	D38	Engine specifications: 4-cyl. turbo dies. eng. 1.6 l/77 kW (4V) TDI common rail Base engine is TF3/TN1/TJ1
4SD	Left vanity mirror: Vanity mirror, left, illuminated	4TD	Right vanity mirror: Vanity mirror, right, illuminated
7Q0	Navigation device: without navigation system	8TC	rear fog lamp: Rear fog light for driving on the right
8WD	Front fog lamp/additional headlamp: Integrated front fog light	GP1	Upgrading measures: Vehicles with special upgrade measures
4P3	Rear of platform module base: Rear floor panel module, type 4	7PA	Platform group class: Platform group class 1





## WYPOSAŻENIE

LICZBA WPISÓW: 192

Kod	Opis	Kod	Opis
1NL	Hubcaps: Trims for alloy wheels	C0Y	Wheels: Alloy wheels 6.5J x 16
8AE	Radios: Radio "RCD310 MP3"	9JB	Smoker's/non-smoker's package: Smoker's package, ashtrays in front and rear
7K0	Tire pressure monitoring system: Without tyre pressure monitor	HH7	tire: Tires 205/55 R16 91V
V0A	Tire suppliers: Tires without specification of tire brand	1G2	Spare wheel/breakdown kit: Spare wheel with full tyre, steel
3QT	Restraint systems, front: 3-point seat belts in front, with tensioner and height adjustment	PH2	Air conditioning Climatronic
PU2	Multi-function leather steering wheel	RGC	"RCD 310" 4 x 20 W, 8 speakers
W32	Equipment package *Poland*	WD4	Anti-theft alarm system "Plus"
WDB	Parallel parking assistant "Park Assist"incl. park distance control	WW1	Winter package
4X3	Side airbag: Side airbag in front, with curtain airbag	6Q2	Gearshift knob/handle: Gearshift knob/handle in leather
2KW	Special labels/plates: Labels in German, French and Dutch	4E0	Locking mechanism for boot lid/cover rear: Tailgate/trunk lid unlocking from outside
3TG	Front seat, left: Sports comfort seat in front, left	3SG	Front seat, right: Sports comfort seat, front, right
QD1	Nameplates for sales name: Nameplates for sales name	9P3	Seat belt check: Seat belt reminder, electric contact in buckle
3ZB	Outer rear seat belts: 3-point seat belts, outer rear with ECE label	3C7	Center rear seat belts: 3-point seat belt for center rear seat
N7H	seat covers: Alcantara/fabric seat covering	3L3	Seat adjustment: Manual height adjustment for front seats
4A3	seat heater: seat heating for front seats separat controlable	3K0	Safety head restraint system: w/o safety head restraint system
7R3	Side lights: Side turn signal lights (white)	7L3	Start-stop system/regenerative braking: Without start/stop system without regenerative braking
8Y1	Horns: Two-tone horn	4KC	Side and rear windows: Side and rear windows in heat-insulating glass
4B0	Protective side molding: with no protective side strip	3Y0	Sunroof roller blind for rear/side windows: without roller blind
9J0	Supertone system and tone sequence control: Without supertone system and tone sequence control	7B2	power outlet: 12 volt socket in luggage compartment
2JD	Bumper: Sports bumpers	0BG	Rear stabilizer: Rear stabilizer
0AH	Front stabilizer bar: Front stabilizer bar	QN0	Drawers under front seats: Without drawers under front seats
2UA	Heavy-duty/sports version: Standard design	8X1	Headlamp washer system: Headlamp washer system
8N4	Windshield wiper intermittent control/light/rain sensor: Windshield wiper intermittent control with potentiometer (four speeds)	3M0	Special approval measures: Without special measures



## WYPOSAŻENIE

LICZBA WPISÓW: 192




Kod	Opis	Kod	Opis
1DG	Nameplate set: Nameplate set "TDI"	9A0	Special alarm systems: Without taxi alarm system
3YQ	Door storage compartments in front: Door pockets without insert mats	1Q0	Mass damper for steering wheels: steering wheel without balance weight
4K3	Door and lid locking system: Central locking w/ radio remote control, interior controls and SAFELOCK	B17	Type approval countries/countries with special requirements: Type approval country Poland
5D1	Carrier frequency for remote control: Carrier frequency 433.92 to 434.42 Mhz	3CA	Partition: without partition
4AF	Door and side trim panels: Door and side trim panel in foam film and woven fabric	0A2	doors: 4 doors
QV0	TV reception/digital radio reception: without TV/digital radio reception	1SA	Front underbody guard: Without additional front underbody guard
1EX	Identification plates: Special identification label for EC for M1 passenger vehicles	2A8	Delivery equipment: Delivery equipment, water border
1T2	First aid kit / warning triangle: warning triangle	9D0	Two-way radio installation preparation: without prepared for two way radio system
9F0	Preparation for rotating beacon/siren combination: Without preparation for rotating beacon/siren combination	9W0	Telephone / telematics: Without car phone preparation/ installation
9TC	Additional warning lights: Additional retro-reflectors (door area)	QG1	LongLife Service Regime: LongLife Service Regime
7E6	Heat accumulator system/auxiliary heater: electric air additional heater	4GF	Windshield Glass: Windshield in heat-insulating glass
8W1	Washer fluid level indicator: Washer fluid level indicator	2WA	Additional tires (snow tires): without spare tyre
0TD	floor mats: Front and rear floor mats	6EA	Additional body panels, side: Without additional side body covers (stone guard)
3B4	Additional child seat anchors: Child seat anchors for child seat system ISOFIX	9M0	Auxiliary heating system: Without auxiliary heater/parking heater











## ARCHIWALNE ZDJĘCIA POJAZDU

LICZBA ZDJĘĆ: 11

Data	Szczegóły	Liczba zdjęć
2015-03-10	--	11



Data	Szczegóły	Liczba zdjęć
		
		
		

### Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez ASDIRECT Sp. z o.o. o tym fakcie.

ASDIRECT Sp. z o.o. nie ponosi odpowiedzialności za treść danych zawartych w Raportach. Treść taka może być niepełna lub niezgodna ze stanem rzeczywistym.

Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi ASDIRECT Sp. z o.o.

Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego.

Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody ASDIRECT Sp. z o.o.

ASDIRECT Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiegokolwiek formie.

ASDIRECT Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez ASDIRECT Sp. z o.o. w jakiegokolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.